

## REMARKS

By the present amendment, Figure 1 has been replaced by new Figure 1 enclosed herewith.

In the Detailed Action section of the Notice of Allowability, the Examiner objected to the drawings because reference character "55" was used to designate both a "sealing o-ring" and the "opposite side face of base part".

The enclosed replacement sheet provides an amended Figure 1 where the "opposite side face of base part" is now designated by reference character "50". This change is believed to address the Examiner's objection.

### Regarding the Allowed Claims

Page 2 of the Notice of Allowability indicates that claims 42-107 are allowed. However, page 1 of the Notice of Allowability indicates that claims 43-107 are allowed, which is believed to be an unintentional error on the part of the Examiner. Since claims 42-107 were pending in the last communication from the Applicants to the office, it is believed that claims 42-107 are the allowed claims, as indicated by the Examiner on page 2 of the Notice of Allowability.

Should the Examiner believe that anything further is desirable to place the application in a better condition for issuance, the Examiner is invited to contact the undersigned at the telephone number listed below.

At the time of filing of the present response, the Office was authorized to charge the fees believed to be necessary to a credit card. In case of any under- or over-payment or should any additional fee be otherwise necessary, the Office is hereby authorized to credit or debit (as the case may be) Deposit Account number 502977.

Respectfully submitted,

/Jonathan David Cutler/

Jonathan D. Cutler, Reg. No. 40,576  
OSLER, HOSKIN & HARCOURT LLP  
Attorneys for the Applicant

OSLER, HOSKIN & HARCOURT LLP  
1000 de la Gauchetière St. West  
Suite 2100  
Montréal, Québec H3B 4W5  
Canada

Tel. (514) 904-5624  
Fax. (514) 904-8101